


REFERENCE 21

A-134

023406-05/26/01-D1

US0311



Bargabos Construction
Company, Inc.

EXCAV
GR/
ROAD CONSTR
SITE DEVELOP
LAND CLEA

R.D. 4, BOX 166A, CANASTOTA, NEW YORK 13032

September 23, 1981

Town Board
Town of Salina
Oneida County, New York
913 Liverpool Road
Liverpool, New York 13088

ATTENTION: DARRELL W. WESTON, SUPERVISOR

RE: SALINA LANDFILL, DIRT FILL & GRADING CONTRACT

Gentlemen:

We are here by requesting an extension of the completion date to July 31, 1982 for our contract to provide dirt fill and grading for the Town of Salina Landfill site.

Due to the extreme wetness which presently exists at the site and the continued amount of rainfall that we have been experiencing it has become highly questionable as to when we will be able to start the project and for how long the site will remain accessible for the equipment that will be required to complete the work.

Upon contract signing it is our intent to start the work at the earliest reasonable date but due to the current adverse conditions that presently exist at the site we are respectfully requesting the extension of the completion date with our guarantee that we will hold our unit prices to July 31, 1982.

Your favorable action regarding this request would be greatly appreciated.

Very Truly Yours,

James P. Wheeler
Vice President

JW:dw

cc: Mr. L. Kane II
Mr. A. Rivisigiano
Mr. K. Haneyin

Phone: (315) 422-9416
(315) 697-9999

A-135

ecology and environment

US0312


REFERENCE 22

A-136

02:340B-05/25/01-D1

US0313

ASSUMPTION



SECTION MAP 73

TOWN OF SALINA
ONONDAGA COUNTY, N.Y.

FOR TAXING PURPOSES ONLY
NOT TO BE USED FOR CONVEYANCE

A-137

C

US0314

THRUWAY


STATE

YORK

14.26⁰ (C)

NEW

File 02/18/11 Entered 02/18/11 18:02:19 Exhibit 3
(Part 6b) Pg 5 of 25



REFERENCE 23

A-139

023408-05/26/01-D1
recycled paper

ecology and environment.

US0316

NAME OF SITE <i>Sacramento</i>	LOCATION (Town, Village, City) <i>Sacramento</i>	COUNTY <i>Oakland</i>
OPERATOR	ADDRESS	ST
OWNER	ADDRESS	

EXPLAIN YES ANSWERS ON REVERSE SIDE

- | | YES | NO |
|---|-------------------------------------|-------------------------------------|
| 1. Burning at Time of Inspection. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Evidence of On-site Burning. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Dumping into Water. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Leachate Observed At The Site. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Leaching into a Water Course. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Refuse not Confined to a Manageable Area. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 7. Unsatisfactory Daily Soil Cover. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 8. Refuse Protruding through Completed Areas. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Improper Spreading and Compaction of the Refuse. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 10. Pooling of Water, Cover Soil Cracking, Soil Erosion, or Improper Slope on Completed Area. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. Evidence of Rodents and Insects. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 12. Blowing Paper Problem. | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 13. Salvaging of Refuse Creating a Nuisance. | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| 14. Approach Road Impassable to Vehicular Traffic During part of the year. | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

CONTROL OF SITE

 Signs Fence and Gate Supervision None

EQUIPMENT AT SITE

Type

Track -

Size

*17- D-8 - 955 Front loaded**Track*

TYPE OF REFUSE DISPOSED

 Residential Commercial Industrial Demolition Agricultural Scavenger

SON INTERVIEWED

Lee Capria - Ed Davies

EXPECTED BY (Signature)

DATE

10/27/72

TIME

*9:20 AM**George E. Shamp*

I (12/71)

TITLE

San Fran Technician

REFERENCE 24

A-141

02-3409-05/25/11-01
recycled paper

ecology and environment

US0318

**DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF SOLID AND HAZARDOUS WASTE
FACILITY INSPECTION REPORT**

- LEACHATE**
1. Leachate is entering surface water.
 2. Leachate is known to be containing groundwater standards.
 3. Water is being placed into water.

BURNING

4. Refuse is burning without permit or not under permit conditions.
5. There is evidence of unapproved propane burning.

COVER

6. Previous day waste is not covered.
7. Refuse is protruding through daily intermediate or final cover.
8. Intermediate or final cover is not in place or properly applied.

GRADING

9. Depression, ponding, craggy cover, or slopes steeper than 1 on 3 exist.
10. Vegetative cover is sparse or inadequate on completed areas.
11. Soil erosion or other drain problems exist.

SEPARATION DISTANCES

12. Waste is closer than 50 feet to site boundaries.
13. Refuse is being placed less than 3 feet above groundwater or bedrock.
14. Waste is being placed too close to surface water.

HABITAT CONDITIONS

15. Odors are detectable off site.
16. Blowing dust or dirt is a nuisance.
17. Papers are uncontrolled or blowing off site.
18. Noise is a nuisance off site.

OPERATION CONTROL

19. Operation Permit conditions are being violated. (List condition)
20. Waste is not sufficiently confined or controlled.
21. Refuse is spread in layers thicker than 2 feet.
22. Refuse is not compacted or compacted insufficiently.
23. The working face height is greater than 10 feet.
24. Equipment on the site is not adequate for proper operation.

Safety AND HEALTH

25. Salvaging is uncontrolled or is creating a safety hazard.
26. Rodents, insects, birds, or other vermin are not controlled.
27. Unsafe conditions or equipment exist. (List items)
28. Methane gas is known to be leaving the site.
29. Access to the site is improper, unsafe, or inadequately controlled.
30. The site is open without an attendant.
31. Information about the site is not posted. (e.g., hours of operation)
32. Access to the operating area is poor or unsafe.

OTHER

33. Uncontrolled leachate is visible on or near the site.
34. The quality of cover material is inadequate.
35. Slope of working face is steeper than 1 on 3.
36. Monitoring wells are not operating.
37. Unapproved wastes have been deposited since last inspection.
38. Operator is unfamiliar with site boundaries, operation plan or permit.
39. Land application of waste to frontenow covered ground or during periods of rain.
40. Solid waste is buried.

FACILITY NAME	SAZINA TOWN LANDFILL	LOCATION	ROUTE 11 TOWNS OF SAZINA
PERSONS INTERVIEWED AND TITLES			

No ONE

SITE SKETCH FORMENTS (Additional sheets attached)

- I INSPECTED THE SITE WITH HENRIETTE HAMER AND EMILY THOMAS OF THE N.Y.S. DEPT. OF HEALTH.
WE WALKED THE PERIMETER OF THE SITE AND OBSERVED SPOT AREAS OF POLLUTION.
I COULD DETECT SOME LEACHATE.
GAS ODORS AS WELL AS ARCS COMING FROM THE NEARBY LEE CREEK TRANSFER STATION.
NO LEACHATE WAS OBSERVED AT THIS TIME.

GENERALLY THE VEGETATION COULD NOT WELL ESTABLISHED EXCEPT FOR A COUPLE OF SPOTS.
THIS SITE HAS BEEN CLOSED SINCE A NUMBER OF YEARS.

INSPECTOR'S NAME	CLAUDIO J. SANTO	DATE	9/18/11	TIME	12:15
2 FACILITY NO.	7	3	4	5	6
7	8	9	10	11	12
13	14	15	16	17	18
19	20	21	22	23	24
25	26	27	28	29	30
31	32	33	34	35	36
37	38	39	40	41	42
43	44	45	46	47	48
49	50	51	52	53	54
55	56	57	58	59	60
61	62	63	64	65	66
67	68	69	70	71	72
73	74	75	76	77	78
79	80	81	82	83	84
85	86	87	88	89	90
91	92	93	94	95	96
97	98	99	100	101	102
103	104	105	106	107	108
109	110	111	112	113	114
115	116	117	118	119	120
121	122	123	124	125	126
127	128	129	130	131	132
133	134	135	136	137	138
139	140	141	142	143	144
145	146	147	148	149	150
151	152	153	154	155	156
157	158	159	160	161	162
163	164	165	166	167	168
169	170	171	172	173	174
175	176	177	178	179	180
181	182	183	184	185	186
187	188	189	190	191	192
193	194	195	196	197	198
199	200	201	202	203	204
205	206	207	208	209	210
211	212	213	214	215	216
217	218	219	220	221	222
223	224	225	226	227	228
229	230	231	232	233	234
235	236	237	238	239	240
241	242	243	244	245	246
247	248	249	250	251	252
253	254	255	256	257	258
259	260	261	262	263	264
265	266	267	268	269	270
271	272	273	274	275	276
277	278	279	280	281	282
283	284	285	286	287	288
289	290	291	292	293	294
295	296	297	298	299	300
301	302	303	304	305	306
307	308	309	310	311	312
313	314	315	316	317	318
319	320	321	322	323	324
325	326	327	328	329	330
331	332	333	334	335	336
337	338	339	340	341	342
343	344	345	346	347	348
349	350	351	352	353	354
355	356	357	358	359	360
361	362	363	364	365	366
367	368	369	370	371	372
373	374	375	376	377	378
379	380	381	382	383	384
385	386	387	388	389	390
391	392	393	394	395	396
397	398	399	400	401	402
403	404	405	406	407	408
409	410	411	412	413	414
415	416	417	418	419	420
421	422	423	424	425	426
427	428	429	430	431	432
433	434	435	436	437	438
439	440	441	442	443	444
445	446	447	448	449	450
451	452	453	454	455	456
457	458	459	460	461	462
463	464	465	466	467	468
469	470	471	472	473	474
475	476	477	478	479	480
481	482	483	484	485	486
487	488	489	490	491	492
493	494	495	496	497	498
499	500	501	502	503	504
505	506	507	508	509	510
511	512	513	514	515	516
517	518	519	520	521	522
523	524	525	526	527	528
529	530	531	532	533	534
535	536	537	538	539	540
541	542	543	544	545	546
547	548	549	550	551	552
553	554	555	556	557	558
559	560	561	562	563	564
565	566	567	568	569	570
571	572	573	574	575	576
577	578	579	580	581	582
583	584	585	586	587	588
589	590	591	592	593	594
595	596	597	598	599	600
601	602	603	604	605	606
607	608	609	610	611	612
613	614	615	616	617	618
619	620	621	622	623	624
625	626	627	628	629	630
631	632	633	634	635	636
637	638	639	640	641	642
643	644	645	646	647	648
649	650	651	652	653	654
655	656	657	658	659	660
661	662	663	664	665	666
667	668	669	670	671	672
673	674	675	676	677	678
679	680	681	682	683	684
685	686	687	688	689	690
691	692	693	694	695	696
697	698	699	700	701	702
703	704	705	706	707	708
709	710	711	712	713	714
715	716	717	718	719	720
721	722	723	724	725	726
727	728	729	730	731	732
733	734	735	736	737	738
739	740	741	742	743	744
745	746	747	748	749	750
751	752	753	754	755	756
757	758	759	760	761	762
763	764	765	766	767	768
769	770	771	772	773	774
775	776	777	778	779	780
781	782	783	784	785	786
787	788	789	790	791	792
793	794	795	796	797	798
799	800	801	802	803	804
805	806	807	808	809	810
811	812	813	814	815	816
817	818	819	820	821	822
823	824	825	826	827	828
829	830	831	832	833	834
835	836	837	838	839	840
841	842	843	844	845	846
847	848	849	850	851	852
853	854	855	856	857	858
859	860	861	862	863	864
865	866	867	868	869	870
871	872	873	874	875	876
877	878	879	880	881	882
883	884	885	886	887	888
889	890	891	892	893	894
895	896	897	898	899	900
901	902	903	904	905	906
907	908	909	910	911	912
913	914	915	916	917	918
919	920	921	922	923	924
925	926	927	928	929	930
931	932	933	934	935	936
937	938	939	940	941	942
943	944	945	946	947	948
949	950	951	952	953	954
955	956	957	958	959	960
961	962	963	964	965	966
967	968	969	970	971	972
973	974	975	976	977	978
979	980	981	982	983	984
985	986	987	988	989	990
991	992	993	994	995	996
997	998	999	999	999	999

EXPLANATION OF YES ANSWERS

- 1- Landfill was burning at time of inspection for underground construction fire.
- 2- There was evidence of burning in this same area.
- 3- Dugout was evident into the sewage area surrounding haul truck. Leachate was observed leaking into sewage area.
- 4- Refuse was not confined to a manageable area; spreading and compacting was not being properly practiced and daily cover was not being applied or the end of each day.
- 5- Refuse was seen protruding throughout the site area.
- 6- Tarpaper stage on whole area.
- 7- Papers were blown throughout areas surrounding site.
- 8- Appearance seems generally not passable in wet weather.

REFUSE SITE SKETCH

LOCATION SKETCH

A-143

recycled paper

ecology and environment

US0320

REFERENCE 25

A-144

02:3400-05/25/01-D1

US0321

March 18, 1986

10:21 BRIGHTON LANDFILL - Copy to File. With Jeff Banikowski. Jeff and I observed minor amounts of leachate along south and southwest toe of old landfill slope. A garden used by Brighton Towers residents is proximity of the old landfill.

D. Abbott

March 19, 1986

10:49-11:51 PARK ST. DUMP - Indiscriminate dumping is taking place again. Chuck Chernoff, Jim Craft and I hiked around the site. We observed protruding refuse, ponding water, leachate emanating from south perimeter along Ley Creek, and from ditch along Route 81. Copy in File.

12:48-1:15 SALINA - Chuck, Jim and I walked the site perimeters. Area fairly well covered, little protruding observed. Leachate not readily observed. Possible contamination from surface water ditch that runs through the site. Possible contamination of Thruway ditch and Ley Creek along landfill perimeter. Inspection stopped short due to lightning, rain and hail storm that moved in. Copy in File.

1:31-2:58 BRIGHTON - Chuck, Jim and I walked the entire perimeter of this site plus up over the top. We observed approx. six small leachate seeps and a couple of surface water impoundments. Landfill gases could occasionally be smelled. Channel 3 News asked me a couple of brief questions concerning sampling. I told them if we found enough surface leachate seep's we would be collecting some water samples. Copy in File.

H. Van Valkenbourg

11:25 OLSI - Gate open. Men taking down larger, white storage garage inside landfill.

11:57 OLSI - Gate wide open. Workers still on site. Spoke with 2 of the 3 workers. They said they were leaving now for the day because it was too windy to finish the job. They have finished taking down the white garage and only need to load the pieces on a truck for removal. They said they would be back Thursday or Friday depending on the weather. They said they do not work for Mr. Tripoli but were hired by him to do the job. They said Mr. Tripoli unlocked the gate for them. I told the two men I would leave also because I couldn't take the responsibility for locking the gate.

No inspection made. Snow off landfill. Temp. in 60s. Workers left their equipment on site.

ACROSS FROM R. W. CLARK CONTRACTING CORP., 5054 SMORAL RD. - 3 piles of lumber, brick, concrete, metal bands, plastic, insulation, paper, soil, plastic piping and metal piping.

Mr. Clark once told me this was his property. Mr. Tripoli told me this was his property. I already left a message with Ron Ryan, Town of Onon, Codes Enforcement Officer, about this.

D. Abbott

March 20, 1986

12:48 SALINA - Collected PCB samples with Mark, Chuck Chernoff and Dick Corcuera of the DEC. See Mark's report. Copy in File.

2:25-3:35 BRIGHTON LANDFILL - To collect leachate samples for PCBs with Mark, Chuck Chernoff, and Dick Corcuera. See Mark's report. Copy in File.


A-145

RÉFÉRENCE 26

A-146

02:3408-08/25/01-01

US0323



Floods delineated in this reach
in greater detail by the Corps
of Engineers, U.S. Army


US0324

REFERENCE 27

A-148

023408-05/26/01-D1

US0325



REFERENCE 28


A-150

02-3409-05/25/01-D1

US0327

New York State Department of Environmental Conservation

Wildlife Resources Center
Information Services
700 Troy-Schenectady Road
Latham, New York 12110



May 2, 1991

Thomas C. Jorling
Commissioner

Sandra Lane
Ecology and Environment, Inc.
368 Pleasantview Drive
Lancaster, New York 14086

Dear Ms. Lare:

We have reviewed the Significant Habitat Unit and the NY Natural Heritage Program files with respect to your request for biological information concerning the Preliminary Site Assessments for two hazardous waste sites in the Syracuse vicinity, Onondaga County.

We have identified a rare plant, the Cornel-leaved Aster (*Aster firmus*), which historically (1949) occurred in the vicinity of the "Salina" site. This rare plant (G5Q S1) may still be present if suitable habitat still exists. We recommend a thorough search of the area by a qualified individual at the proper time of the year.

Our files are continually growing as new habitats and occurrences of rare species and communities are discovered. In most cases, site-specific or comprehensive surveys for plant and animal occurrences have not been conducted. For these reasons, we can only provide data which have been assembled from our files. We cannot provide a definitive statement on the presence or absence of species, habitats or natural communities. This information should not be substituted for on-site surveys that may be required for environmental assessment.

This response applies only to known occurrences of rare animals, plants and natural communities and/or significant wildlife habitats. You should contact our regional office, Division of Regulatory Affairs, at the address enclosed for information regarding any regulated areas or permits that may be required (e.g., regulated wetlands) under State law.

If this project is still active one year from now we recommend that you contact us again so that we may update this response.

Sincerely,

Burrell Buffington
Significant Habitat Unit

Encs.

cc: Reg. 7, Wildlife Mgr.

A-151

New York Heritage Program is supported in
part by The Nature Conservancy ecology and environment

recycled paper

US0328

REFERENCE 29

A-152

02:3408-06/26/91-D1

US0329

9/26/07
9/26/07

STATE ID #: 1000
STATE CLASS : XL
DOH RANKING : 1
DEC RANKING : 1
HRS SCORES : SM 11.11
SFE 0
SDC 62.50

BUREAU OF TOXIC SUBSTANCE ASSESSMENT
HAZARDOUS WASTE SITE INSPECTION REPORT

IDENTIFYING INFORMATION

NAME: Town of Salina Landfill

ADDRESS: 6101 E St. Syracuse, NY 13212

OWNER: Town of Salina

ADDRESS & PHONE NO.: 201 School Road, Liverpool NY 13088 315-457-2779

EMERGENCY CONTACT: T. Supervisor

ADDRESS & PHONE NO.: 201 School Rd. Liverpool NY 315-457-2779

REGION: 7

DOH REGION: Syracuse

COUNTY: Otsego

TOWN: Salina

DRANGLE MAP: Syracuse West Quad.

PECTORS & DATE: Henry H. Barnes, R.S. / E. Thomas & Dan DATE: 8/20/87

Alt 4)

Site Data

(ACRES): 120 acres

TERRAIN: Hilly

FLAT : X

URBAN : X

URBAN : X

RURAL : X

INDUSTRIAL : X

MUNICIPAL : X

OTHER : X

ACTIVE : X

INACTIVE : X closed in 1970

EXPOSED AND SUSPECTED USERS: T. Salina, General Motors, Fleet Fuel Division

REMANENTS OF CONCERN:

Vapor : -

Contact : -

Groundwater (C) : -

Groundwater (V) : -

KNOWN CONTAMINATION:

On Site

Off Site

Air : -

Groundwater : -

Surface Water : -

Drinking Water : -

Surface Soil : -

Sub Surface Soil : -

Site Status

Inspection :
Investigation :
Negotiation :
Litigation :
Remediation :

NHS Corporation 12/27/86

Agencies Involved:

DOH :
DEC :
DOL :
EPA : ~~NYD9605352~~
County :

Comments:

Former Municipal sanitary填埋場, approx 120 acres, bordered by Leg Creek on the south (over 5 acres of wetlands area). No landfilled before Leg Creek.) LF violations when operational included: on-site burning, dense infiltration, leachate, leachate into a water course, unsat. daily exit evap., improper spreading & evaporation of refuse.

LF is well covered in the majority. Only a very few areas were visible, mostly roadsides & minimal odors. These are ^{designed} wet areas w/ Marsh grass for infiltration.

No leachate visible during (8/20/87)

The area is filled w/ old "dumps" - one across Leg Creek from the Cellar another further down went to Crown-Kinde Co. (7R N.Y. dumped)

3.1

Residential

single family residences : Yes
apartments/condominiums : No - limited arrangements, ie. Condo's
large houses - 4 family packages.

Agricultural

truck farming : None
dairy farming : None
livestock : None

Commercial/Industrial

: 1.1acres
0

Open Space

parks : Not sufficient
playgrounds : Not sufficient
ballfields : Not sufficient

Undeveloped : Some, marshy, Thruway Highway, 81 interchange, River Way - 3.2
with bridge.

Sensitive Targets

schools : None within 1000 ft.
hospitals : None
churches : None without

Specific Targets Identified During Inspection

: None

Complicating Factors. There are other covered dumps in the area; a trash
transfer station adjacent to 77 N. St. smells!

rail yards : No
oil depots : No
power stations : No

Future Use : None proposed

2. Toxicity - Contaminants of Concern

Table 2-2 Waste Compounds: Quantities and Toxicity

Waste	Quantity (Tons)
G40T. Paint and Buffing Sludge	36,300 Tons
PCB contaminated hydraulic oil	37,000 Tons
Pesticides	
solvents	
PCB laden floor absorbents	10,000 Tons
Bailey Fly Ash	
Waste paint thinner + reducer	22 tons
PCB-contaminated fill ^{and} cover material = dredge spoils from Ley Creek. Located at GM/Fisher Grille. Known to have discharged PCB's to Ley Creek on	

ENVIRONMENTAL SAMPLING / ANALYTICAL DATA

Air A	Subsurface Soil . . . G	Onsite
Drinking Water . . . B	Sediment H	Offsite
Ground Water . . . C	Sludge J	Residue
Surface Water . . . D	Leachate K	Drum.
Lagoon, Pond . . . E	Background L	Other
Surface Soil . . . F		

Chemical	CAS No.	Sampling Code No.	Result	Sampling Code No.
Acenanthylene	208-96-8		3500 ug/kg	
Fluorene	86-73-7	MF	4300 ug/kg	
Phenanthrene	85-01-8	MF	24,000 ug/kg	NH
Anthracene	120-12-7	MF	7900 ug/kg	
Dibenzanthene	208-44-0	MF	4100 ug/kg	ME
(bis)benzopyrene	191-24-2	MF	4400 ug/kg	NH
oronaphthalene	83-32-9	MF	3600 ug/kg	
Dibenzofuran	132-64-9	MF	2300 ug/kg	
	...	MF	24,000 ug/kg	NH

Onsite Contact

Target Populations - Estimate values when possible. Use values from Table 3.1 Only if no data available.

Site Use	Number of Persons	Avg. Hours per Day
Recreational Vehicle Users	20	1.0
Parking "beer drinkers"	10	2.0

Reasons for Adjustments, if Used:

Estimate the number of persons ingesting plants at the site: O

A-157

ONONDAGA COUNTY, NEW YORK

73

able substrata are the major limitations for nonfarm uses.

representative profile of Lyons silt loam, in a in the town of Lafayette, 100 feet west of Road, 1,300 feet north of Amidon Road, 3,700 north of U.S. Highway 20:

-0 to 7 inches, very dark gray (10YR 3/1) silt loam; common, medium, distinct, dark-brown and dark reddish-brown root mottles; moderate, medium, granular structure; friable; many roots; 5 percent coarse fragments; neutral; clear, wavy boundary.

g-7 to 11 inches, grayish-brown (10YR 5/2) silt loam; common, medium, distinct yellowish-brown mottles and dark-brown and dark reddish-brown root mottles; moderate, medium, subangular blocky structure parting to moderate, medium, granular; friable; common fine roots; 5 percent coarse fragments; neutral; clear, wavy boundary.

g-11 to 22 inches, grayish-brown (10YR 5/2) silt loam; common, fine and medium, distinct yellowish-brown and light-gray mottles; few fine, distinct, dark-brown and dark reddish-brown root mottles; weak, coarse, subangular blocky structure; firm, slightly sticky; few fine roots; common fine and medium pores; 10 percent coarse fragments; neutral; gradual, wavy boundary.

3g-22 to 34 inches, grayish-brown (10YR 5/2) gravelly loam; common, medium, distinct yellowish-brown and few, medium, faint gray mottles; weak, medium and coarse, subangular blocky structure; friable; few fine and medium pores; 15 percent coarse fragments; mildly alkaline (weakly calcareous); gradual, wavy boundary.

34 to 50 inches, grayish-brown (10YR 5/2) gravelly loam; weak, thick, platy structure; firm; 25 percent coarse fragments; moderately alkaline (strongly calcareous).

The soil ranges from 20 to 40 inches in thickness. Depth carbonates ranges from 12 to 40 inches. Depth to bedrock is less than 40 inches and is generally more than 6 feet. Content of coarse fragments ranges from 5 to 30 percent between depths of 10 and 40 inches and from 20 to 60 percent below a depth of 40 inches. The upper 10 inches of soil generally formed in local alluvium and is the only part that is generally free of coarse fragments or is less than 5 percent by volume.

The A₁ and A₂ horizons range from black (N 2/0) to dark grayish-brown (10YR 3/2). In unlimed areas reaction in the A₁ horizon ranges from medium acid to neutral.

The B horizon ranges from olive gray (5Y 4/2) to gray (5YR 4/2) and has higher chroma mottles ranging from few to many. Texture of the fine-earth fraction ranges from fine sandy loam to light clay loam. Reaction in the B horizon goes from slightly acid to moderately alkaline (calcareous). The C horizon ranges from dark gray (5Y 4/1) to pinkish-gray (5YR 6/2) with or without higher chroma mottles. Texture of the fine-earth fraction is fine sandy loam, loam, or silt loam that is platy, firm, and moderately alkaline (calcareous). Lyons soils are closely associated with the somewhat poorly drained Kendaia, Appleton, and Darien soils. All formed in illuvial material.

as silt loam (Ly).—This level or nearly level soil flats or depressions on uplands that receive surface or seepage from adjacent higher lying soils. Areas are smaller than 20 acres and only a few are larger than 30 acres.

Mixed with this soil in mapping are small spots of somewhat poorly drained Kendaia, Appleton, Darien, and Manheim soils on slight knolls or around the edges of the mapped area. These better drained soils make up as much as 20 percent of some areas, but have little effect on use and management. Also mixed are small spots of very poorly drained Canandaigua soils or Palms muck in depressions or along

drainageways generally near the center of larger mapped areas. These wetter soils make up as much as 15 percent of some areas, and they require extensive drainage for crops.

If undrained, this soil is suited to short-season hay crops, pasture, and trees. Only a few undrained areas are used for crops. If adequately drained, this soil is suited to most crops commonly grown in the county, especially annual short-season row crops. This soil responds readily to drainage if adequate outlets are available. Capability unit IVw-3; woodland suitability group 4w1.

Made Land, Chemical Waste

Made land, chemical waste (Ma) consists of bed areas of chemical waste material. It includes both active beds on which waste is deposited and older beds on which vegetation is becoming established.

The waste material is residue from various chemical products. It is pumped as a slurry into diked beds where it is allowed to settle. The clear water or clear solution, which contains sodium chloride and calcium chloride, is then carefully drained off, and the material is consolidated by further drying. The waste beds are gradually built up to a predetermined height by diking with an impervious core material and coating the outside of the dike with gravel and soil material on which vegetation is established. The enclosed area is then filled by pumping in controlled amounts of slurry, which is allowed to settle, drain, and dry.

The fresh waste material is about 50 percent calcium carbonate, 11 percent calcium hydroxide, 11 percent calcium chloride, 9 percent sodium chloride, 5.5 percent silica, 4.5 percent calcium oxide, 4 percent magnesium oxide, 2.5 percent calcium sulfate, and 2 percent aluminum and iron oxides (6). Reaction (pH) is generally more than 10.

The residual material in the older beds, after draining and leaching, is about 68 percent calcium carbonate, 1 percent calcium chloride, 11 percent silicon dioxide, 12 percent calcium oxide, 7 percent magnesium oxide, and 2 percent calcium sulfate (6). Reaction (pH) is 8.0 to 8.5.

This material has a siltlike texture and has little or no structural development. It is moderately well drained and somewhat poorly drained on the higher terraces and somewhat poorly drained and poorly drained on lower terraces near lake level. These physical conditions are suitable for lime-tolerant plants that can further tolerate somewhat impeded drainage and reduced aeration (6). The material is practically devoid of nitrogen, phosphorus, and potassium.

Fertilizer test-plot results indicate phosphorus is most limiting, but the best plant growth is secured by using a complete fertilizer of a 1-2-1 ratio along with such added organic matter as sewage sludge.

Vegetation begins to grow on the beds after 20 to 25 years. This length of time is needed for toxic salts to leach from the top 1 to 2 feet of the beds.

The hazard of erosion and frost heaving on the exposed beds are major factors in preventing establishment of vegetation. After adequate vegetative cover is established, however, these hazards are eliminated or greatly reduced.